Yealink SIP IP Phone-T46G Release Note of Version 71

1. Introduction

- Firmware Version：28.71.0.155 upgrade to 28.71.0.170
- Applicable Models：SIP- T46G
- Release Date：September 29, 2013

2. New Features

Added the Limited to upgrade feature via auto provisioning.

3. Bug Fixes

1. Fixed the issue that the T46 didn't display the status when using the feature of push XML.

2. Fixed the issue that the input method of LDAP didn't switched via auto provisioning and it also can't save the last input format.

3. Fixed the issue that the main speaker could also hear the local ring tone and set on the server when the T46 received a 180 Message.

4. Fixed the issue that the dial tone of Great Britain was incorrect.

5. Fixed the Memory leaks issue during the IPV4 and IPV6 were enable at the same time.

4. Description to the new added features

Added the new configuration item of M7 as fallow:
auto_provision.downgrade_enable = 0/1，0 is default.
It was unlimited for the user to degrade or upgrade the firmware via auto provision
When this configuration item was enable (the value was 1).on the contrary, the user didn't degrade when the value was 0.

The definition of relegation:
1. To upgrade the version number is smaller than the current version (the second version number).
2. To upgrade the version number is consistent, and the small version number is smaller than the current version(the fourth version number).

e.g.:

If the current version is 2.70.0.140 and the value of the configuration item is 0, the user can't degrade the firmware to 2.61.0.140 or 2.70.0.130,unless the configuration item is set as 1（auto_provision.downgrade_enable = 1）.

Note:

It is only allowed the user to use the limited to upgrade feature via auto provision, the web upgrade without this feature.

Version	Editor	Modification Time
V 1.0	Dennis	2013/08/22
V1.1	Samuel	2013/10/09

Yealink SIP IP Phone-T46G Release Note of Version 71

1. Introduction

- Firmware Version：From 28.71.0.80 To 28.71.0.155
- Applicable Models：SIP- T46G
- Release Date：August 21, 2013

2. Bug Fixes

1. Fixed the issue that T46G didn't send the model, Mac address and other information to the server so that it can't be recognized by server during Auto Provision.

2. Fixed the issue that some SIP Server Hosts weren't able to pass the verification of domain in T46G of version 71.

3. Fixed the issue that T46G can't obtain the related CFG files from the FTP server during the Auto Provision process.

4. Fixed the issue that T46G wasn't able to obtain the language file after download the related CFG files from the server.

5. Fixed the issue that T46G wasn't able to display the voicemail alert.

6. Fixed the issue that T46G failed to register the Zultys MX250 r80.0.3 server, server sent 400 bad request reply.

7. Fixed the issue that user can't remote control the T46G via CRM software even they include the username and password in the action URI command.

8. Fixed the issue that Auto Answer Delay of T46G wasn't able to function.

9. Fixed the issue that user enabled the Logon Wizard but it probabilistic disappeared after rebooted the phone.

10. Fixed the issue that time zone name of France was not uniformed among T46G, T3X and T2X series.

11. Fixed the issue that T46G can't properly play the ringtone after ringtone configuration via Auto Provision.

12. Fixed the issue that T46G can't support side tone as same as T2X series.

13. Fixed the issue that action URI of T46G can't properly work and receive a 302 reply.

14. Fixed the issue that T46G can't properly play an uploaded ringtone and other default ringtones after user had tried to play this uploaded ringtone.

15. Fixed the issue that the V flag still be displayed even the VPN of T46G wasn't connected.

16. Fixed the issue that the settings of backlight time in CFG file wasn't as same as web page settings.

17. Fixed the issue that some configuration parameters for auto provision mode of T46G were different from T2X series.

18. Fixed the issue that the configuration parameters for time zone wasn't uniformed with T3X and T2X series in CFG file.

19. Fixed the issue that the statements of replace rule in Dial Plan were not uniform between version 71 and version 70.

20. Fixed the issue that T46G wasn't able to adjust the volume of ringtone on the web page of Ring Tones.

21. Fixed the issue that T46G wasn't able to recognize a domain named syslog as a server.

22. Fixed the issue that T46G probabilistic rebooted either idle status or during call setup, not when a call is established.

23. Fixed the issue that labels were too short on the LCD of T46G.

24. Fixed the issue that time error occurred during manual modification when user set daylight-saving time on the web page of T46G.

25. Fixed the issue that key press sound disappeared during pressed left and right navigation key when user picked up the handset.

26. Fixed the issue that hard key for Mute of T46G unable to be used after user pressed the DTMF key to enter a conference.

27. Fixed the issue that alert-info for distinctive ringing of T46G can't properly function.

28. Fixed the issue that T46G were unable to download the both of common.cfg and mac-address.cfg files via RPS for Auto Provision.

29. Fixed the issue that the label of account of T46G had limitation for some special symbols such as & and !.

30. Fixed the issue that T46G had limitation for web page password settings.

31. Fixed the issue that time setting of T46G wasn't synchronized after finished Auto Provision.

32. Fixed the issue that the light of 10th line key was not on after user had finished BLF/Call Park settings and unable to flashing when there was a call from the monitored phone number.

Version	Editor	Modification Time
V 1.0	Dennis	2013/08/22