

## Yealink SIP IP Phone-T41G Release Note of Version 71

### 1. Introduction

- Firmware Version: 36.71.0.40&41 upgrade to 36.71.0.50&51
- Applicable Models: SIP- T41G
- Release Date: September 29, 2013

### 2. New Features

Added the Limited to upgrade feature via auto provisioning.

### 3. Bug Fixes

1. Fixed the issue that the dial tone of Great Britain was incorrect.
2. Fixed the Memory leaks issue when the IPV4 and IPV6 were enable at the same time.

### 4. Description to the new added features

**Added the new configuration item of M7 as follow:**

auto\_provision.downgrade\_enable = 0/1, 0 is default.

It was unlimited for the user to degrade or upgrade the firmware via auto provision  
When this configuration item was enable (the value was 1).on the contrary, the user didn't degrade when the value was 0.

**The definition of relegation:**

1. To upgrade the version number is smaller than the current version (the second version number).
2. To upgrade the version number is consistent, and the small version number is smaller than the current version(the fourth version number).

**e.g.:**

If the current version is 2.70.0.140 and the value of the configuration item is 0, the user can't degrade the firmware to 2.61.0.140 or 2.70.0.130,unless the configuration item is set as 1 ( auto\_provision.downgrade\_enable = 1 ) .

**Notes:**

It is only allowed the user to use the limited to upgrade feature via auto provision, and the web upgrade without this feature.

Version	Editor	Modification Time
V 1.0	Samuel	2013/10/12